

INTRODUCTION

CybTouch Converter is a new function allowing the conversion of products created with PC-ModEva (or PC1200) into CybTouch format files, and so being able to use them on a CybTouch 8 or CybTouch 12.



This function is available from software version T on. If your current software version is older, please contact support@cybelec.ch.

HOW TO CONVERT A PART-PROGRAM?

1. Check that the version of PC-ModEva (or PC1200) installed on your PC is recent enough to contain CybTouch Converter.



MENU → Welcome

The **DNC Software Version** must end with a 'T'

WELCOME		00/04/20 14:15																																																															
MACHINE N°	677	USER																																																															
ORIGIN	CYBELEC SA	Rue des Utlins 27	1400 Yverdon Switzerland																																																														
DNC SOFTWARE VERSION																																																																	
DNC	508FFF	ENC																																																															
MDX		SPEED	mm/s																																																														
		LENGTH	mm																																																														
		FORCE	Ton																																																														
MEMORY CAPACITY	TOTAL	FREE	FORCELENGTH																																																														
			Ton/m																																																														
DNC PROGRAM	963876800	KB	78.314																																																														
IN	INTERNAL	963876800	KB																																																														
WEIGHT			kg/mm³																																																														
HEAP	20971 / 20971	KB																																																															
LANGUAGE			GB																																																														
ACTIVE PERIPHERALS																																																																	
MACHINE	INTERNAL	PRODUCTS	INTERNAL																																																														
PINCHES	INTERNAL	DIES	INTERNAL																																																														
		COMPLEMENTS	INTERNAL																																																														
KEY SERIAL N°	IG-00119	NOT FOR SALE																																																															
OPTIONS IN KEY																																																																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	19	20	21	22	24	25	-30	-32	+33	-37	-38	-39	41	-42	-44	-46	-47	-49	-52	-53	57	-58	-60	-61	164	-65	-66	-67	68	169	-71	-72	-73	74	75	76	77	78	-79	80	-81	-82	83	84	-85	-86	-87	-88	-8..
SERVICE		SINCE																																																															
TOTAL MINES REALIZED																																																																	
TIME COUNTER		h	min																																																														

2. Activate the **CybTouch Converter** function in the machine parameter.



MENU → Machine parameters → MENU → Preferences 2


MACHINE PARAMETERS		PREFERENCES 2	
Induction aids			YES
USBRS232 angle measurement			NO
Machine parking feature			NO
Compiling covering correction according to measured angles			NO
CybTouch converter			YES


Parameter **CybTouch Converter** must be set to **YES**

3. In the List of Products' page, start the CybTouch Converter.



MENU → Cancel → List of products → ACTIONS → CybTouch Converter

4. Select the destination folder for the converted files.
5. Select the part(s) that you want to convert and touch this  button.



6. The program-parts are now converted and located on your PC or USB key. They can be directly transferred on your CybTouch, using the USB Transfer page (see the CybTouch User Manual).

